

SPECIAL NOTICE

The Borough has experienced a significant increase of fees for 2010 from the South Monmouth Sewage Authority due to increased flows in 2009. The Borough will be conducting inspections and testing of the system to determine what is causing the increased flows.

It is believed that ground water and tidal flooding are the principal contributors to this cost.

The Public Works Department will perform work to better seal manholes in those areas that have road flooding. They will also inspect lines during rain events to pinpoint flows that could be due to sump pumps being illegally connected to the sanitary sewer system.

Code Enforcement, during inspections, will be checking to see that sump pumps are not illegally hooked up to the sanitary sewer system.

Sump pumps are strictly prohibited from connection to the Borough of Manasquan Sewer System Ordinance 1713-96 Section 22-18.

In addition, mushroom sewer vent caps must be at least three feet above ground.

Also Section 22-16 of Ord. 1713-96 requires all sewer laterals from the main to the building be maintained sound at all times. Clean-out caps at ground level must have water tight caps to prevent infiltration.

Violation of the above ordinances may result in a fine of \$1,250.00 and/or discontinuance of water service.

These violations will be strictly enforced in the future.